



(reporting Authority)

MEDITERRANEAN MEMORANDUM OF UNDERSTANDING  
**PORT STATE CONTROL**  
MINISTRY OF PUBLIC WORKS & TRANSPORT  
DIRECTORATE GENERAL OF LAND & MARITIME TRANSPORT

(address)

Georges Picot St. STARCO Bldg 3<sup>rd</sup> Floor  
Beirut - Lebanon

(telephone)  
(telefax)  
(email)

+961-1-371644  
+961-1-371647  
ministry@transportation.gov.lb

copy to : - master  
- head office  
- PSCO  
if ship is detained, copy to:  
- flag State  
- Recognized organization, if applicable

01. Name of ship

RHOSLIS

2. IMO number

8630344

3. Date of final report

4. Place of inspection

Beirut

DEFICIENCIES FOUND AND FOLLOW UP ACTIONS \*\*\*

Code	Defective item	Nature of defect <sup>1)</sup>	Convention ref. <sup>2)</sup>	Ground for detention	Action taken (AT)	Follow up AT, if applicable	Additional comments	RO resp. <sup>3)</sup>
9232	Cleanliness of Engine Room	Dirty	594-1/CD-1/R	28.7		30	Engine Room is dirty	<input type="checkbox"/>
0717	Jacketed high pressure lines	Not as required	594-11/CH-2	R152.9		30	Main Engine drain pipes (DO) of double skin system are not connected properly with leak back	<input type="checkbox"/>
0108	Lighting	Inoperative				17	Several lamps in E/R	<input type="checkbox"/>
3108	Pipes	Poorly maintained				17	Main Engine Manifold	<input type="checkbox"/>
13102	Thermometers	Missing				17	Main Engine Thermometer (E.W.)	<input type="checkbox"/>
13107	Other Machinery	Leaking				17	Excessive oil leakage from Lub oil Separator	<input type="checkbox"/>

Name:

(duly authorized PSCO of reporting authority)

Signature

Lebanese P.S.C. Officer  
Eng. Mohamed Moustapha

Lebanese P.S.C. Officer  
Capt. Hazem Saad

\*\*\*/ Masters, Shipowners and/or Operators are advised that detailed information on the inspection may be subject to publication ([www.medmou.org](http://www.medmou.org))  
1 This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.  
2 To be completed in the event of a detention. (for non-convention ships: 500 GT as reference only)  
3 Follow up AT per deficiency to be introduced by other(s) MED MOU PSCO's  
Revision 2